



Pipe Assessment Report

**CCTV Inspection report produced on behalf of:
SAMPLE**

CCTV Inspection Project Scope

A pressurised CCTV survey was undertaken on a potable water pipeline to confirm internal pipe condition as part of a zonal study investigation scheme. All inspections were undertaken via existing type 2 fire hydrants using PIPA Technology approved for use in potable water mains.

Pressurised Pipe CCTV Internal Inspection Report

Equipment Testing Details:

Calibration and Testing undertaken by:	C Webster
---	-----------

Equipment Information:

System Used:	Hydrocam S	Visual Check:	30/10/2022
ID Number:	HCS102	Sanitised:	30/10/2022
Purpose Used:	CCTV Survey Potable Water	Pat Test Date:	30/09/2022
Pressure Tested:	30/10/2022	Pat Test Due:	30/12/2022

Chlorination Details:

Chlorination Mixture:	31/10/2022
Chlorine/Water:	1 part to 1000
Technician Name:	Oliver Whetstone-James

Chlorination of Fittings Details:

Chlorination Tablet:	1 unit
Time held on fittings:	09.28 to 09.33am
Technician Name:	Oliver Whetstone-James

Asset Operation Details:

Time arrival on site:	09.25am
Operation of hydrant:	09.36am
Isolation of hydrant:	09.56am
Time of departure:	10.05am

Pressurised Pipe CCTV Internal Inspection Report




Location:	SAMPLE	Inspection Date:
Client:	SAMPLE	31/10/2022
Client contact:	SAMPLE	Reference ID
API Staff on site:	Oliver Whetstone-James & Joe Hunt	SAMPLE

Pipe Details:

Pipe Material:	CI	Pipe Coating:	None
ID (Nominal):	90mm	Internal Lining:	PU
Age:	1912	Reason for Survey:	Condition assessment
Pressure:	4 Bar	Distance of Survey:	10 metres

Condition Grading: *Pipe grading a visual representation only

Hydraulic Grade:	2
Asset Condition:	Average
Depth of riser:	0.4 metres

Grade 1	Grade 2 Slight	Grade 3 0-20%	Grade 4 20-40%	Grade 5 >40%
				

Supporting Photo information:



Site Location



Camera insertion point hydrant

Pressurised Pipe CCTV Internal Inspection Report

Pressure reading taken on site (actual):



Location Map of Survey:




Pressurised Pipe CCTV Internal Inspection Report

Pressurised CCTV Survey Internal Video Stills and Notes:

Title 1



Title 2



Pressurised Pipe CCTV Internal Inspection Report

Direction 1 with flow

Title 3



Title 4



Pressurised Pipe CCTV Internal Inspection Report

Title 5



Title 6



Pressurised Pipe CCTV Internal Inspection Report

Title 7




Title 8



Pressurised Pipe CCTV Internal Inspection Report

Title 9




Title 10



Pressurised Pipe CCTV Internal Inspection Report

Direction 2 against flow

Title 11



Title 12




Pressurised Pipe CCTV Internal Inspection Report

Title 13




Title 14




Pressurised Pipe CCTV Internal Inspection Report

Title 15




Title 16



Pressurised Pipe CCTV Internal Inspection Report

Title 17



Title 18



Pressurised Pipe CCTV Internal Inspection Report

Inspection comments:

A pressurised CCTV inspection was undertaken on a pipeline to ascertain a condition assessment

Chapter 8 signage and barriers supplied by API

Entry was via a fire hydrant

Entry point was located on a road carriageway

The camera/cable was fully chlorinated during insertion through a chlorine chamber and standpipe configuration

Direction 1 with flow direction

- Medium levels of residual sedimentation identified during survey
- Medium levels of tuberculation identified within the pipeline
- Low levels of debris identified during survey
- Pipeline appears to be in an average condition
- Joints identified at 0.4 metres
- Survey ended at 5 metres due to distance being achieved

Direction 2 against flow direction

- Medium levels of residual sedimentation identified during survey
- Low levels of tuberculation identified within the pipeline
- Low levels of debris identified during survey
- Pipeline appears to be in an average condition
- Survey ended at 5 metres due to distance being achieved

Additional Comments

- GIS states CI with PU Lining & Profuse PE
- CI with PU Lining confirmed
- Profuse PE not present
- Pipeline is recommended for cleaning scheme

Pressurised Pipe CCTV Internal Inspection Report

Additional Photos:

Title 1



Image of hydrant bowl condition

Title 2



Image of hydrant cap in situ

Pressurised Pipe CCTV Internal Inspection Report

Additional Photos:

Title 1



Image of site on arrival

Title 2



Image of site on departure

Pressurised Pipe CCTV Internal Inspection Report

RAMS Statement:

All CCTV activities were completed by adhering to RAMS submitted by API on pressurised potable water pipe inspection surveys and no debris has been observed during this process.

All stages of this procedure are recorded using video and photo data and are available on request.

-End of Inspection Report-

Produced By:	Carl Read		
Ref:	CR_001	Date:	31/10/2022
Approved By:	Fabio Orlandi		
Ref:	FO_001	Date:	4/11/2022

Pressurised Pipe CCTV Internal Inspection Report



**API UK Ltd
Friar Gate Studios
Ford Street
Derby
DE11EE**

**Tel 01332 258361
www.api-uk.com**

This document is protected by copyright and may not be reproduced in whole or in part by any means without the approval in writing of Advanced Pipe Inspection UK Limited. No Person, other than the Customer for whom it has been prepared, may place reliance on its contents and no duty of care is assumed by API toward any Person other than the Customer. Reactive work undertaken from this report content is solely the responsibility of the client, It is recommended that the recorded video results is also studied to understand asset condition.

This document must be read in its entirety and is subject to any assumptions and qualifications expressed therein. Elements of this document contain detailed technical data which is intended for analysis only by persons possessing requisite expertise in its subject matter.