



Pipe Assessment Report

CCTV/Acoustic Commissioncam™ leakage and inspection report
produced on behalf of:
SAMPLE

CCTV & Acoustic Inspection Project Scope

A pressurised CCTV and acoustic survey was undertaken on a new installation potable water pipeline to locate a possible leak or leaks within a pipeline section. The survey was completed to also confirm that the pipe was clean and free of debris as part of the commissioning procedure.

Pressurised Pipe Internal CCTV & Acoustic Report

Equipment Testing Details:

Calibration and Testing undertaken by:	S Lewthwaite
---	--------------

Equipment Information:

System Used:	Pipepod Hydrostatic & Commissioncam	Visual Check:	25-1-21
ID Number:	018-1100	Sanitised:	25-1-21
Purpose Used:	Acoustic Survey Potable Water	Pat Test Date:	2-1-21
Pressure Tested:	25-1-21	Pat Test Due:	2-4-21

Chlorination Details:

Chlorination Mixture:	N/A
Chlorine/Water:	N/A
Technician Name:	N/A

Pressurised Pipe Internal CCTV & Acoustic Report


Location:	SAMPLE	Inspection Date:
Client:	SAMPLE	27-1-21
Client contact:	SAMPLE	Hydrant Reference ID
API Team Leader:	Jamie Hadley	API-SAMPLE

Pipe Details:

Pipe Material:	DI	Pipe Coating:	Yes paint
ID (Nominal):	650 mm	Internal Lining:	Cement
Age:	New Installation	Reason for Survey:	Leak Detection
Pressure:	11 Bar	Distance of Survey:	590.00 Metres

Condition Grading: *Pipe grading a visual representation only

Hydraulic Grade:	1-2
Asset Condition:	New installation
Risk of Fracture:	High

Grade 1	Grade 2 Slight	Grade 3 0-20%	Grade 4 20-40%	Grade 5 >40%
				

Supporting Photo information:



Site Location B: System entry point




System exit point top of hill:

Pressurised Pipe Internal CCTV & Acoustic Report

Pressure reading (Actual on site):



Location Map of Survey:



Pressurised Pipe Internal CCTV & Acoustic Report

Pressurised CCTV Survey Internal Video Stills and Notes:
Direction 1 towards pit A



Start of survey




Debris identified

Pressurised Pipe Internal CCTV & Acoustic Report



Poor water clarity



Poor water clarity

Pressurised Pipe Internal CCTV & Acoustic Report



Poor water clarity



Good water clarity

Pressurised Pipe Internal CCTV & Acoustic Report



Air pocket identified



Air pocket identified

Pressurised Pipe Internal CCTV & Acoustic Report



Main image



Main image

Pressurised Pipe Internal CCTV & Acoustic Report



Wide joint image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image possible gasket and wide joint (this point recorded an acoustic POI)

Pressurised Pipe Internal CCTV & Acoustic Report




Some acoustic interest identified and non-uniform joint



Wide Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report




Main image




Debris on joint image

Pressurised Pipe Internal CCTV & Acoustic Report




Bend image



Bend image with debris identified

Pressurised Pipe Internal CCTV & Acoustic Report




Joint image



Possible failure of cement lining

Pressurised Pipe Internal CCTV & Acoustic Report



Bend image



Main image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image with debris identified

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image




Joint image with debris identified

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Main image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image




Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image




Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Bend image



Bend image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image with possible gasket identified



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Main image



Joint image with failure of lining identified

Pressurised Pipe Internal CCTV & Acoustic Report



Main image with blistering of lining identified



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Main image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Main image



Joint image possible gasket identified

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image with possible gasket identified



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Main image



Main image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Main image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image with possible gasket identified



Main image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image with possible gasket identified



Main image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Main image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



Joint image



Joint image

Pressurised Pipe Internal CCTV & Acoustic Report



End of survey




Wide joint at exit point identified

Pressurised Pipe Internal CCTV & Acoustic Report

Inspection comments:

- A pressurised CCTV & acoustic survey was undertaken on a new installation potable water pipeline with a detailed leakage sweep
- Entry was via a DN100 & DN80 valve pipe configuration
- No chlorination required during survey
- Chapter 8 signage and barriers was provided by client
- The Commissioncam™ entry point was located in an excavation area in field
- The retrieval point was located in an excavation area in field
- Client pre-installed the pipeline cable using a tethered swab approach

Additional Information – Acoustic Scanning Details (leak analysis)




SG1
Full spectrograph

SG2

SG3


Pressurised Pipe Internal CCTV & Acoustic Report



0-100m No acoustic point of interest identified




100-225m No acoustic point of interest identified




225-350m possible acoustic point of interest identified at 300 metre area

Pressurised Pipe Internal CCTV & Acoustic Report



350-500m no acoustic point of interest identified



500-600m acoustic point of interest identified (depressurising at end of survey)

Post Analysis Results

One clear acoustic band signature is observed during the post analysis of the recorded inspection footage; graph also indicates pressurisation and depressurisation of the sensor.

- SG1 illustrates the sensor moving at the start of the survey
- SG2 illustrates the sensor moving during the survey
- SG3 illustrates water injection and water passing of the exit chamber

No other acoustic peaks identified (leaks) during the data post analysis of the acoustic data. PIPA Software identifies leaks and illustrates points of interest with solid red banding (see spectrograph above).

Sporadic sound spikes are also present (sensor drag or contacting pipe wall only).

Possible leak detected during survey undertaken at 11 bar pressure only.

Pressurised Pipe Internal CCTV & Acoustic Report

Acoustic post analysis

Both by using software analysis and by listening to the recorded file, there is a short acoustic point of interest identified at 4 hours, 18 minutes and 18 seconds, this equates to the area of 300 metres from sensor insertion point. Site investigations should focus on pipe joints within this area.

Areas of interest identified on video stills listed in red on the report.

CCTV post analysis

Observing the CCTV footage the pipe contains medium to high levels of pipe ingress, this is concentrated mainly at the bottom of the hill section, and up to a distance of 50 metres, which may be removed using a potable adapted jetting system.

Areas of entrapped air pockets are also observed during the pipe inspection survey.

Pressurised Pipe Internal CCTV & Acoustic Report

Additional Information – Site photos



Pressurised Pipe Internal CCTV & Acoustic Report



Pressurised Pipe Internal CCTV & Acoustic Report

-End of Inspection Report-

Reviewed By:	C Webster		
Ref:	CW_001	Date:	29-1-21
Approved By:	F Orlandi		
Ref:	FO_001	Date:	30-1-21

Pressurised Pipe Internal CCTV & Acoustic Report



**API UK Ltd
Friar Gate Studios
Ford Street
Derby
DE11EE**

**Tel 01332 258361
www.api-uk.com**

This document is protected by copyright and may not be reproduced in whole or in part by any means without the approval in writing of Advanced Pipe Inspection UK Limited. No Person, other than the Customer for whom it has been prepared, may place reliance on its contents and no duty of care is assumed by API toward any Person other than the Customer. Reactive work undertaken from this report content is solely the responsibility of the client, It is recommended that the recorded video results is also studied to understand asset condition.

This document must be read in its entirety and is subject to any assumptions and qualifications expressed therein. Elements of this document contain detailed technical data which is intended for analysis only by persons possessing requisite expertise in its subject matter.